



**Aalto University**  
**School of Electrical**  
**Engineering**

# **Lecture 10: Field-Oriented Control**

## **ELEC-E8405 Electric Drives**

Marko Hinkkanen

Autumn 2022

# Learning Outcomes

After this lecture and exercises you will be able to:

- ▶ Explain the basic principles of field-oriented control of a permanent-magnet synchronous motor
- ▶ Draw and explain the block diagram of field-oriented control
- ▶ Calculate the operating points of the motor in rotor coordinates


# Outline

## **3-Phase Inverter**



Field-Oriented Control

Current and Voltage Limits


# 3-Phase Inverter



# DC-DC Converter vs. 3-Phase Inverter



# Space Vector of the Converter Output Voltages



- ▶ Zero-sequence voltage does not affect the phase currents
- ▶ Reference potential of the phase voltages can be freely chosen

$$\begin{aligned} \mathbf{u}_s^s &= \frac{2}{3} \left( u_{an} + u_{bn}e^{j2\pi/3} + u_{cn}e^{j4\pi/3} \right) && \text{Neutral } n \text{ as a reference} \\ &= \frac{2}{3} \left( u_{aN} + u_{bN}e^{j2\pi/3} + u_{cN}e^{j4\pi/3} \right) && \text{Negative DC bus } N \text{ as a reference} \end{aligned}$$


► Converter output voltage vector

$$\begin{aligned} \mathbf{u}_s^s &= \frac{2}{3} \left( u_{aN} + u_{bN}e^{j2\pi/3} + u_{cN}e^{j4\pi/3} \right) \\ &= \frac{2}{3} \left( q_a + q_b e^{j2\pi/3} + q_c e^{j4\pi/3} \right) U_{dc} \end{aligned}$$

where  $q_{abc}$  are the switching states (either 0 or 1)

► Vector (1, 0, 0) as an example

$$\mathbf{u}_s^s = \frac{2U_{dc}}{3}$$



# Switching-Cycle Averaged Voltage

- ▶ Using PWM, any voltage vector inside the voltage hexagon can be produced in average over the switching period

$$\bar{\mathbf{u}}_s^s = \frac{2}{3} \left( d_a + d_b e^{j2\pi/3} + d_c e^{j4\pi/3} \right) U_{dc}$$

where  $d_{abc}$  are the duty ratios (between 0...1)

- ▶ Maximum magnitude of the voltage vector is  $u_{\max} = U_{dc}/\sqrt{3}$  in linear modulation (the circle inside the hexagon)
- ▶ PWM can be implemented using the carrier comparison
- ▶ Only switching-cycle averaged quantities will be needed in the following (overlining will be omitted for simplicity)

---

The 3-phase PWM and the space-vector current controller can be realized using similar techniques as we used in connection with the DC-DC converters and the DC motors, respectively. However, details of these methods are out of the scope of this course.



# Outline


3-Phase Inverter

**Field-Oriented Control**

Current and Voltage Limits

# Permanent-Magnet Synchronous Motor

- ▶ Current distribution produced by a 3-phase winding is illustrated in the figure
- ▶ Torque is constant only if the supply frequency equals the electrical rotor speed  
 $\omega_m = d\vartheta_m/dt$
- ▶ For controlling the torque, the current distribution has to be properly placed in relation to the rotor
- ▶ Rotor position has to be measured (or estimated)



# Field-Oriented Control

- ▶ Resembles cascaded control of DC motors
- ▶ Automatically synchronises the supply frequency with the rotating rotor field
- ▶ Torque can be controlled simply via  $i_q$  in rotor coordinates
- ▶ Field-oriented control of other AC motors is quite similar to that of a surface-mounted permanent-magnet synchronous motor considered in these lectures

# Synchronous Motor Model in Rotor Coordinates

- ▶ Stator voltage

$$\mathbf{u}_s = R_s \mathbf{i}_s + \frac{d\boldsymbol{\psi}_s}{dt} + j\omega_m \boldsymbol{\psi}_s$$

- ▶ Stator flux linkage

$$\boldsymbol{\psi}_s = L_s \mathbf{i}_s + \boldsymbol{\psi}_f$$

- ▶ Torque is proportional to the q component of the current

$$\tau_M = \frac{3n_p}{2} \operatorname{Im} \{ \mathbf{i}_s \boldsymbol{\psi}_s^* \} = \frac{3n_p}{2} \psi_f i_q$$

# Space-Vector and Coordinate Transformations


- ▶ Space-vector transformation (abc/ $\alpha\beta$ )

$$\mathbf{i}_s^s = \frac{2}{3} \left( i_a + i_b e^{j2\pi/3} + i_c e^{j4\pi/3} \right)$$


- ▶ Transformation to rotor coordinates ( $\alpha\beta$ /dq)

$$\mathbf{i}_s = \mathbf{i}_s^s e^{-j\vartheta_m}$$

- ▶ Combination of these two transformations is often referred to as abc/dq transformation
- ▶ Similarly, the inverse transformation is referred to as dq/abc transformation




# Fast Current Controller in Rotor Coordinates




- ▶ Absolute rotor position  $\vartheta_M$  has to be measured (or estimated)
- ▶ Current reference  $i_{s,ref} = i_{d,ref} + j i_{q,ref}$  is calculated in rotor coordinates

The current controller could consist, for example, of two similar real-valued PI-type controllers (one for  $i_d$  and another for  $i_q$ ).

# Field-Oriented Controller



- ▶ Control principle  $i_{d,ref} = 0$  minimises the resistive losses
- ▶ Speed controller is not needed in some applications





# Outline

3-Phase Inverter

Field-Oriented Control

**Current and Voltage Limits**


# Stator Voltage

- ▶ In steady state,  $d/dt = 0$  holds in rotor coordinates
- ▶ Steady-state stator voltage


$$\begin{aligned} \mathbf{u}_s &= j\omega_m \boldsymbol{\psi}_s \\ &= j\omega_m (L_s \mathbf{i}_s + \boldsymbol{\psi}_f) \\ &= j\omega_m (L_s i_d + \boldsymbol{\psi}_f + jL_s i_q) \end{aligned}$$

when  $R_s = 0$  is assumed


- ▶ **Voltage increases with the speed**
- ▶ Maximum voltage magnitude  $u_{\max}$  is limited by the DC-bus voltage  $U_{dc}$



# Field Weakening Above the Base Speed



Below the base speed:  $i_d = 0$



Above the base speed:  $i_d < 0$   
in order to reduce  $|\psi_s|$

---

If a synchronous machine had a field winding instead of the permanent magnets,  $\psi_f$  could also be varied.


# Current Limit

- ▶ Current limit

$$i_s^2 = i_d^2 + i_q^2 \leq i_{\max}^2$$

- ▶ Example figure

- ▶ Rated motor current  $i_N$
- ▶ Maximum converter current is assumed to be  $1.5i_N$
- ▶ Motor tolerates short-time overload currents due to its longer thermal time constant



# Voltage Limit


- Voltage limit

$$u_s^2 = \omega_m^2 \psi_s^2 \leq u_{\max}^2$$

can be represented as a speed-dependent stator-flux limit

$$\psi_s^2 = (L_s i_d + \psi_f)^2 + (L_s i_q)^2 \leq \frac{u_{\max}^2}{\omega_m^2}$$

- Example figure: current loci at two different speeds as the torque varies



# Summary of Control Principles

- ▶ Control principle below the base speed

$$i_{d,\text{ref}} = 0 \quad \text{and} \quad i_{q,\text{ref}} = \frac{2\tau_{M,\text{ref}}}{3n_p\psi_f}$$

- ▶ Field weakening ( $i_d < 0$ ) can be used to reach higher speeds
  - ▶ Nonzero  $i_d$  causes losses  $(3/2)R_s i_d^2$
  - ▶ Risk of overvoltages if the current control is lost
  - ▶ Risk of demagnetizing the permanent magnets in some machines
- ▶ Current and voltage limits have to be taken into account