



Aalto University
School of Electrical
Engineering

Lecture 9: Elementary Single-Phase Machines and Lossless Magnetic Field

ELEC-E8402 Control of Electric Drives and Power Converters

Marko Hinkkanen

Spring 2018

Single-Phase Machines

- ▶ Single-phase machines **are not used** in real applications
- ▶ Why should we study them?
- ▶ To get more thorough **understanding of fundamental concepts**
 - ▶ Flux linkages
 - ▶ Conservative magnetic field systems
 - ▶ Selection of state variables
 - ▶ Modeling concepts introduced are very **general and powerful**
- ▶ For simplicity, 2-pole machines will be considered here
- ▶ More poles can be easily taken into account

Outline

Permanent-Magnet Machine



Salient-Pole Machine

Lossless Magnetic Field

Voltage Equations

Airgap Field Produced by PMs



- ▶ Ferrite PMs are cheap and easy to manufacture
- ▶ Rare-earth magnets (e.g. NdFeB, SmCo) provide much higher energy products, but they are expensive and difficult to manufacture and handle



Assumed uniform radial air-gap flux density

Equivalent Current Source


- ▶ PMs can be modeled with an equivalent field winding
- ▶ Permeability of the magnets is approximately the same as that of air
- ▶ Current i_f is constant



Assumed uniform radial air-gap flux density

Induced Voltage

- ▶ Rotor rotates at $\omega_m = d\vartheta_m/dt$
- ▶ Magnetic field moves at $v = r\omega_m$ with respect to the conductors
- ▶ Voltage $B\ell v$ is induced in each conductor
- ▶ N turns in the coil
- ▶ Induced voltage $e_a = 2NrlB\omega_m$ is proportional to the angular speed



Phase Voltage

- ▶ Phase voltage

$$u_a = R_a i_a + \frac{d\psi_a}{dt}$$


- ▶ Phase flux linkage

$$\psi_a = L_a i_a + \psi_{af}(\vartheta_m)$$

where L_a is the self-inductance and ψ_{af} is the flux linkage due to the PMs

- ▶ Based on the geometry

$$\psi_{af} = 2Nr\ell B \left(\frac{\pi}{2} - \vartheta_m \right) \quad \text{when } 0 \leq \vartheta_m \leq \pi$$



Phase Voltage


- ▶ Voltage can be expressed as

$$u_a = Ri_a + L_a \frac{di_a}{dt} + e_a$$

- ▶ Voltage induced by the magnets

$$\begin{aligned} e_a &= \frac{d\psi_{af}}{dt} = \frac{d\psi_{af}}{d\vartheta_m} \frac{d\vartheta_m}{dt} \\ &= -2NrlB\omega_m \end{aligned}$$

which is the same result as earlier



The sign in the expression for e_a is valid at $0 < \vartheta_m < \pi$, cf. the following waveforms.

Torque Production


- ▶ Forces $F = NBl_i a$ act on both coil sides
- ▶ Opposite counterforces act on the rotor
- ▶ **Electromagnetic torque**

$$T_m = -2NrlBi_a$$

is proportional to the current



- ▶ Mechanical power

$$p_m = T_m \omega_m = e_a i_a$$





The sign in the expression for T_M is valid at $0 < \vartheta_m < \pi$, cf. the following waveforms.

Example Waveforms



The waveform of the current i_a is chosen such that the torque T_m becomes constant.

Simple Distributed Winding





- ▶ Waveforms approximately sinusoidal

$$\psi_{af} = \psi_1 \cos(\vartheta_m)$$
$$e_a = -\omega_m \psi_1 \sin(\vartheta_m)$$

- ▶ PM-flux constant $\psi_1 \propto NrlB$

Example Waveforms: Ideal Sinusoidally Distributed Winding



Outline


Permanent-Magnet Machine

Salient-Pole Machine


Lossless Magnetic Field

Voltage Equations


Reluctance Machine



- ▶ Ideal anisotropy assumed above (with constant leakage inductance)
- ▶ Inductance L_a depends on the rotor position
- ▶ Flux linkage $\psi_a = L_a(\vartheta_m)i_a$




Simple Distributed Winding





- ▶ Ideal anisotropy assumed above (with constant leakage inductance)
- ▶ If spatial harmonics are omitted

$$\psi_a = [L_0 + L_2 \cos(2\vartheta_m)]i_a$$



PM Reluctance Machine



- Approximate flux linkage

$$\psi_a = [L_0 - L_2 \cos(2\vartheta_m)]i_a + \psi_1 \cos(\vartheta_m)$$

Salient-Pole Machine With Field Winding

- ▶ Field winding in the rotor
- ▶ Flux linkages

$$\psi_a = L_a(\vartheta_m) i_a + L_{af}(\vartheta_m) i_f$$


$$\psi_f = L_{af}(\vartheta_m) i_a + L_f i_f$$

where

$$L_a(\vartheta_m) = L_0 + L_2 \cos(2\vartheta_m)$$

$$L_{af}(\vartheta_m) = M \cos(\vartheta_m)$$

- ▶ How to determine torque T_m of salient-pole machines?



Outline

Permanent-Magnet Machine

Salient-Pole Machine

Lossless Magnetic Field

Voltage Equations

Lossless Magnetic Field


Understanding lossless magnetic field systems often helps in developing machine models for control purposes

- ▶ Very general and powerful concept
- ▶ Only assumption is that the magnetic field is lossless (conservative)
- ▶ Forces and torques in complex electromechanical systems can be determined
- ▶ Independent of machine type, number of terminals, number of poles, etc.
- ▶ Most lumped-parameter electric machine models are based on it
- ▶ Magnetic saturation and spatial harmonics can be taken into account
- ▶ Core losses can be modeled outside the lossless field system

Lossless Magnetic Field

Stored magnetic field energy W_m

- ▶ is a state function, depending only on its independent state variables
- ▶ is independent of the path used to reach the state
- ▶ can be determined completely if the electrical port relations are known
- ▶ can be evaluated by means of numerical techniques (e.g. FEM) or measurements




Example System: Single-Phase Machine With Field Winding

- ▶ Two electrical ports and one mechanical port
- ▶ Stored field energy

$$W_m = W_m(\psi_a, \psi_f, \vartheta_m)$$

where ψ_a , ψ_f , and ϑ_m are independent state variables

- ▶ This example system is considered in the following



► Power balance

$$\frac{dW_m}{dt} = i_a \frac{d\psi_a}{dt} + i_f \frac{d\psi_f}{dt} - T_m \frac{d\vartheta_m}{dt}$$


► Currents

$$i_a = \frac{\partial W_m(\psi_a, \psi_f, \vartheta_m)}{\partial \psi_a}$$

$$i_f = \frac{\partial W_m(\psi_a, \psi_f, \vartheta_m)}{\partial \psi_f}$$

► Torque

$$T_m = - \frac{\partial W_m(\psi_a, \psi_f, \vartheta_m)}{\partial \vartheta_m}$$



Lossless Field System Should Satisfy Reciprocity Conditions

- ▶ Incremental mutual inductances should be equal in any operating point

$$\frac{\partial i_a}{\partial \psi_f} = \frac{\partial i_f}{\partial \psi_a}$$

- ▶ If multiple mechanical ports, analogous conditions hold for them as well
- ▶ Conditions between electrical and mechanical ports


$$\frac{\partial i_a}{\partial \vartheta_m} = -\frac{\partial T_m}{\partial \psi_a} \qquad \frac{\partial i_f}{\partial \vartheta_m} = -\frac{\partial T_m}{\partial \psi_f}$$

Integration Path for the Field Energy Can Be Chosen Freely

- ▶ For illustration purposes $\psi_f = 0$ assumed
- ▶ Integration along Path 1

$$W_m(\psi_a, \vartheta_m) = \int_0^{\psi_a} i_a(\psi'_a, 0) d\psi'_a - \int_0^{\vartheta_m} T_m(\psi_a, \vartheta'_m) d\vartheta'_m$$

- ▶ We should know $T_m(\psi_a, \vartheta_m)$



- ▶ Integration along Path 2

$$W_m(\psi_a, \vartheta_m) = \int_0^{\psi_a} i_a(\psi'_a, \vartheta_m) d\psi'_a$$

since $T_m(0, \vartheta_m) = 0$

- ▶ Torque is not needed in Path 2





Illustration of Field Energy and Coenergy

- ▶ For illustration purposes $\psi_f = 0$ assumed
- ▶ Area of the rectangle $\psi_a i_a$
- ▶ Relation of coenergy to field energy

$$W_m + W'_m = \psi_a i_a$$

- ▶ Magnetically linear case: $W_m = W'_m$



Field Energy and Coenergy

- ▶ Field energy

$$W_m(\psi_a, \psi_f, \vartheta_m) = \int_0^{\psi_a} i_a(\psi'_a, \psi_f, \vartheta_m) d\psi'_a + \int_0^{\psi_f} i_f(0, \psi'_f, \vartheta_m) d\psi'_f$$

- ▶ Coenergy

$$W'_m(i_a, i_f, \vartheta_m) = \int_0^{i_a} \psi_a(i'_a, i_f, \vartheta_m) di'_a + \int_0^{i_f} \psi_f(0, i'_f, \vartheta_m) di'_f$$

- ▶ Relation of coenergy to field energy

$$W_m + W'_m = \psi_a i_a + \psi_f i_f$$

- ▶ Torque is typically easier to calculate from coenergy

Torque from Coenergy

- ▶ Power balance

$$\frac{dW'_m}{dt} = \psi_a \frac{di_a}{dt} + \psi_f \frac{di_f}{dt} + T_m \frac{d\vartheta_m}{dt}$$


- ▶ Flux linkages

$$\psi_a = \frac{\partial W'_m(i_a, i_f, \vartheta_m)}{\partial i_a}$$

$$\psi_f = \frac{\partial W'_m(i_a, i_f, \vartheta_m)}{\partial i_f}$$

- ▶ Torque

$$T_m = \frac{\partial W'_m(i_a, i_f, \vartheta_m)}{\partial \vartheta_m}$$



Analytical Example

- ▶ Assume a magnetically linear machine with the flux linkages

$$\psi_a = L_a(\vartheta_m)i_a + L_{af}(\vartheta_m)i_f$$

$$\psi_f = L_{af}(\vartheta_m)i_a + L_f i_f$$

where the inductances are

$$L_a(\vartheta_m) = L_0 + L_2 \cos(2\vartheta_m) \quad L_{af}(\vartheta_m) = M \cos(\vartheta_m)$$


- ▶ Coenergy

$$W'_m(i_a, i_f, \vartheta_m) = \frac{1}{2} [L_0 + L_2 \cos(2\vartheta_m)] i_a^2 + M \cos(\vartheta_m) i_a i_f + \frac{1}{2} L_f i_f^2$$


- ▶ Torque

$$T_m = -M \sin(\vartheta_m) i_a i_f - L_2 \sin(2\vartheta_m) i_a^2$$

Torque



Currents i_a and i_f are constant



Field current i_f is constant

Outline


Permanent-Magnet Machine

Salient-Pole Machine

Lossless Magnetic Field

Voltage Equations

Inclusion of Voltage Equations



Voltage Equations: Flux Linkages as State Variables

- ▶ Voltage equations

$$\frac{d\psi_a}{dt} = u_a - R_a i_a \qquad \frac{d\psi_f}{dt} = u_f - R_f i_f$$

where the currents are known static functions of the state variables

$$i_a = i_a(\psi_a, \psi_f, \vartheta_m) \qquad i_f = i_f(\psi_a, \psi_f, \vartheta_m)$$

- ▶ Electromagnetic torque is the input for the mechanical subsystem

$$T_m = T_m(\psi_a, \psi_f, \vartheta_m)$$

and the state variable ϑ_m is the output of the mechanical subsystem

- ▶ This set of equations is very **simple to implement**

The torque expression $T_m = T_m(i_a, i_f, \vartheta_m)$ could be used as well since the currents $i_a = i_a(\psi_a, \psi_f, \vartheta_m)$ and $i_f = i_f(\psi_a, \psi_f, \vartheta_m)$ are known.

Voltage Equations: Currents as State Variables

- ▶ If the currents are used the state variables, the representation of the voltage equations becomes complex, for example

$$\frac{d\psi_a}{dt} = \frac{\partial\psi_a}{\partial i_a} \frac{di_a}{dt} + \frac{\partial\psi_a}{\partial i_f} \frac{di_f}{dt} + \frac{\partial\psi_a}{\partial \vartheta_m} \frac{d\vartheta_m}{dt} = u_a - R_a i_a$$

- ▶ In general case, all the partial derivatives are functions of i_a , i_f , and ϑ_m
- ▶ In the magnetically linear example case

$$L_a(\vartheta_m) \frac{di_a}{dt} + L_{af}(\vartheta_m) \frac{di_f}{dt} + \left[\frac{\partial L_a(\vartheta_m)}{\partial \vartheta_m} i_a + \frac{\partial L_{af}(\vartheta_m)}{\partial \vartheta_m} i_f \right] \frac{d\vartheta_m}{dt} = u_a - R_a i_a$$

and similarly for the rotor voltage equation

Further Reading

- ▶ H. H. Woodson and J. R. Melcher, *Electromechanical Dynamics*, John Wiley & Sons, 1968.
- ▶ A. E. Fitzgerald, C. Kingsley, Jr., and S. D. Umans, *Electric Machinery*, 6th ed., McGraw-Hill, 2003.